

Inspection Photos

Location Name: Railay West 2833-1NH Location ID 438066, Spill ID #465340

Inspection Date: 6/14/2019



Photo 1 – Location Sign at pad entrance, not at gate near access from US Hwy 85.



Photo 2 – Runoff and rills from south side of pad where access road enters pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Railay West 2833-1NH Location ID 438066, Spill ID #465340

Inspection Date: 6/14/2019



Photo 3 – Rill developing around site berm where access road enters pad on south side of pad.



Photo 4 – Diesel AST either leaks or was overfilled. Stain on ground has diesel odor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Railay West 2833-1NH Location ID 438066, Spill ID #465340

Inspection Date: 6/14/2019



Photo 5 – Looking east at combustor, source of reported release. Pad has been scraped.



Photo 6 – East side of combustor in corner of pad, looking south.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Railay West 2833-1NH Location ID 438066, Spill ID #465340

Inspection Date: 6/14/2019



Photo 7 – On southeast corner of location looking south toward path of spill from combustor reported on 6/13/2019.



Photo 8 – Spill traveled offsite onto rangeland. Looking south from fence on south edge of pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Railay West 2833-1NH Location ID 438066, Spill ID #465340

Inspection Date: 6/14/2019



Photo 9 – From east lobe of south end of spill extent looking north.



Photo 10 - From west lobe of south end of spill extent looking north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Railay West 2833-1NH Location ID 438066, Spill ID #465340

Inspection Date: 6/14/2019



Photo 11 – Two track that developed outside location southern fence line from equipment access spill area. Looking west.



Photo 12 – Two track that developed outside location southern fence line from equipment access spill area. Looking east. Deminimus oily soil present along two track.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Railay West 2833-1NH Location ID 438066, Spill ID #465340

Inspection Date: 6/14/2019



Photo 13 – Residual oil impacts in AST secondary containment.



Photo 14 – Stormwater mixed with oil inside AST secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Railay West 2833-1NH Location ID 438066, Spill ID #465340

Inspection Date: 6/14/2019



Photo 15 – Oil stains on ASTs from former oil release.



Photo 16 – Diesel fuel leaked from AST stored on northwest corner of location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources