

# Inspection Photos

API: 05-009-06568

Operator: ENERGY ALLIANCE COMPANY

Inspection Date: 6/13/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06568 | Date: 6/13/2019

## Inspection Photos



**Photo 1.** Facing west at the location. Pipe risers have been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06568 | Date: 6/13/2019

## Inspection Photos



**Photo 2.** Facing east. Vegetation has not reestablished on 50 ft. x 50 ft. area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06568 | Date: 6/13/2019

## Inspection Photos



**Photo 3.** Facing north at the surrounding reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06568 | Date: 6/13/2019