

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/17/2019
Submitted Date:
06/17/2019
Document Number:
687904904

FIELD INSPECTION FORM

Loc ID 333612 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 16 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159068	UIC DISPOSAL	AC	09/13/2001		-	SITTON DISPOSAL 1	AC
159077	UIC DISPOSAL	AC	09/13/2001		-	SITTON WATER DISPOSAL #2	AC

General Comment:

[Site inspection with photos at the end of this report.](#) [Conducted MIT test of UIC injection wellhead.](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on tanks have no fire hazard number for produced water and need to be updated.		
Corrective Action:	Comply with Rule 210.b.	Date:	07/17/2019
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact information posted on signs.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	TRASH		
Comment:	Orange safety fencing partially buried along East side of 100bbl tank berm.		
Corrective Action:	Remove trash per Rule 603.f.	Date:	06/27/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Chain link privacy fence around location.		
Corrective Action:		Date:	
Equipment:			
Type: Other	# 1		corrective date
Comment:	Injection well pumping equipment in metal building.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	MCC for electric driven pumps.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On heated tanks.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Plumbed to surface in PVC tube.		
Corrective Action:		Date:	

Type: Flow Line	# 4		
Comment:	Flowline from outlet of injection pumping equipment to wellhead. Inlet piping from gathering system to tanks on location. 1" flowline for heated steel tank fuel gas.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Injection wellheads.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	1000 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Insufficient	Base Sufficient	Adequate
Comment:	Northern and western walls inside secondary containment, liner has come loose and is not mounted to the wall.			
Corrective Action:	Repair secondary containment per Rule 906.d.(1)			
				Date: 07/17/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 159068 Type: UIC API Number: - Status: AC Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: 1600

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: _____
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: _____
			AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: 5 Year Tbg psi: 1225 Csg psi: 1.7 BH psi: 0.0

Insp. Status: Pass

Comment: Conducted MIT test on well. Last 5 year MIT completed in 6/19/2014 (Doc# 200407773).
-Start pressure 1600psig
-@5min: 1590psig, @10min: 1580psig, @15min: 1580psig, @20min: 1580psig, @30min: 1580psig final.

Corrective Action: _____ Date: _____

Facility ID: 159077 Type: UIC API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					
Waddles	Pass					
Compaction	Pass	Gravel	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904905	Tank Labeling produced water fire hazard.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852346
687904906	Trash.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852347
687904907	Secondary containment liner.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852348
687904908	Secondary containment liner.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852349