

Caerus Piceance LLC
API # 05-045-15432
Inspection # 696600153



Photo #1 Photo from entrance of location.



Photo #2 Separators on location.

Caerus Piceance LLC
API # 05-045-15432
Inspection # 696600153



Photo #3 Photo of tank Battery



Photo #4 Photo of Wellheads

Caerus Piceance LLC
API # 05-045-15432
Inspection # 696600153



Photo # 5 Berm at SW corner of location need maintenance.

Caerus Piceance LLC
API # 05-045-15432
Inspection # 696600153



Photo # 6 Berm at SW corner of location need maintenance.



Photo # 7 Berm at SW corner of location need maintenance.