

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2019

Submitted Date:

06/18/2019

Document Number:

689900891**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
LEVENGOD JOHN		jlevengood07@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412232	PIPELINE	AC	05/04/1998		-	BACA GAS GATHERING SYSTEM 412232	RI

**General Comment:**This is a location inspection.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location sign shows incorrect operator.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	07/18/2019

Emergency Contact Number:			
Comment:	Emergency contact is missing		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	07/18/2019

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	There are weeds growing around the equipment and on soil pile.		
Corrective Action:	Comply with Rule 603.f . Control weed growth.	Date:	07/18/2019
Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment on location. 2 GMR sheds, pipe, scrap metal.		
Corrective Action:	Comply with Rule 603.f . Remove unused equipment.	Date:	07/18/2019
Type	OTHER		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f . Remove pipe risers.	Date:	07/18/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	The fence around the location is in disrepair.		
Corrective Action:	Comply with 1002.a.3. Repair fence.	Date:	07/18/2019

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900892	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4853592">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4853592</a>