



DC-16 CO2 Well Location Photos
API #05-033-06185 / Facility ID #463479
FIR #693900266 / Form 4 #402079696



Photo 1: View of the southern project area from the southeastern corner facing westward. Storm water erosion controls installed.



Photo 2: View of the eastern project area from the northeastern corner facing southward. Storm water controls in place.



Photo 3: View of the project area from the northeastern corner facing center.



Photo 4: Perimeter controls installed along access road to prevent topsoil loss.