

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/18/2019

Submitted Date:

06/18/2019

Document Number:

685101169

FIELD INSPECTION FORM
 Loc ID 430616 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430615	WELL	PR	08/01/2018	OW	123-36212	BYDALEK 28C-20HZ	PR
430618	WELL	PR	01/01/2019	OW	123-36214	BYDALEK 4N-20HZ	PR
430620	WELL	SI	10/01/2017	OW	123-36216	BYDALEK 28N-20HZ	SI
430622	WELL	SI	09/01/2018	OW	123-36217	BYDALEK 3N-20HZ	SI
430624	WELL	PR	09/12/2013	OW	123-36219	BYDALEK 29C-20HZ	PR
430626	WELL	PR	09/12/2013	OW	123-36220	BYDALEK 29N-20HZ	PR
430629	WELL	PR	09/12/2013	OW	123-36223	BYDALEK 30C-20HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	4' barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Red AG fencing		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 10		
Comment:	Automation and Electric boxes		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			

Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric		
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with oil tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		40.117090,-104.693330
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: <u>430615</u>	Type: <u>WELL</u>	API Number: <u>123-36212</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430618</u>	Type: <u>WELL</u>	API Number: <u>123-36214</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430620</u>	Type: <u>WELL</u>	API Number: <u>123-36216</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>430622</u>	Type: <u>WELL</u>	API Number: <u>123-36217</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>430624</u>	Type: <u>WELL</u>	API Number: <u>123-36219</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430626</u>	Type: <u>WELL</u>	API Number: <u>123-36220</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430629</u>	Type: <u>WELL</u>	API Number: <u>123-36223</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. Continuing Education Inspection.	medinaj	06/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101170	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4854505