

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2019

Submitted Date:

06/18/2019

Document Number:

685101175

**FIELD INSPECTION FORM**

Loc ID 426111 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426096	WELL	SI	11/01/2018	OW	123-34579	MELBON RANCH 13-17	SI
426103	WELL	SI	11/01/2018	GW	123-34585	MELBON RANCH 14-17	SI
426105	WELL	SI	11/01/2018	OW	123-34587	MELBON RANCH 2-4-17	SI
426108	WELL	SI	10/01/2018	OW	123-34590	MELBON RANCH 23-17	SI
426360	WELL	TA	11/12/2018	OW	123-34663	MELBON RANCH 3A-17H	TA

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: 6' chain link fence

Corrective Action:

Date: \_\_\_\_\_

Type LOCATION

Comment: 6' chain link

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: VRT # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: LACT # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 20

Comment: automation and electric

Corrective Action:

Date: \_\_\_\_\_

Type: Plunger Lift # 11

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Bird Protectors # 20

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Pump Jack # 2

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Horizontal Heated Separator # 13

Comment:

Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 8		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric motor		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	500 BBLs	STEEL AST		40.132700,-104.693280
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 426096 Type: WELL API Number: 123-34579 Status: SI Insp. Status: SI

Facility ID: 426103 Type: WELL API Number: 123-34585 Status: SI Insp. Status: SI

Facility ID: 426105 Type: WELL API Number: 123-34587 Status: SI Insp. Status: SI

Facility ID: 426108 Type: WELL API Number: 123-34590 Status: SI Insp. Status: SI

Facility ID: 426360 Type: WELL API Number: 123-34663 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">At time of inspection location appears to be in compliance with COGCC rules. Continuing Education Inspection.</a>	medinaj	06/18/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101176	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4854508">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4854508</a>
685101177	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4854509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4854509</a>