

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2019

Submitted Date:

06/18/2019

Document Number:

685101178

FIELD INSPECTION FORM

Loc ID 305691 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@Anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281228	WELL	SI	01/01/2019	GW	123-23362	CROWDER 1-18	SI
431665	WELL	PR	08/15/2013	OW	123-36718	CROWDER 16N-19HZ	PR
431666	WELL	PR	08/13/2013	OW	123-36719	CROWDER 16C-19HZ	PR
431667	WELL	SI	01/01/2019	OW	123-36720	CROWDER 38N-19HZ	SI
431668	WELL	PR	01/01/2019	OW	123-36721	CROWDER 15N-18HZ	PR
431670	WELL	AL	09/22/2015	LO	123-36722	CROWDER 37N-18HZ	AL
431672	WELL	PR	08/27/2013	OW	123-36724	CROWDER 36N-18HZ	PR
431673	WELL	PR	08/27/2013	OW	123-36725	CROWDER 15C-18HZ	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Ancillary equipment # 3

Comment: Automation

Corrective Action:

Date: _____

Type: Bradenhead # 3

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift # 3

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 281228 Type: WELL API Number: 123-23362 Status: SI Insp. Status: SI

Facility ID: 431665 Type: WELL API Number: 123-36718 Status: PR Insp. Status: PR

Facility ID: 431666 Type: WELL API Number: 123-36719 Status: PR Insp. Status: PR

Facility ID: 431667 Type: WELL API Number: 123-36720 Status: SI Insp. Status: SI

Facility ID: 431668 Type: WELL API Number: 123-36721 Status: PR Insp. Status: PR

Facility ID: 431670 Type: WELL API Number: 123-36722 Status: AL Insp. Status: AL

Facility ID: 431672 Type: WELL API Number: 123-36724 Status: PR Insp. Status: PR

Facility ID: 431673 Type: WELL API Number: 123-36725 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. Continuing Education Inspection.	medinaj	06/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101179	Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4854510