

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2019

Submitted Date:

06/19/2019

Document Number:

693800646

**FIELD INSPECTION FORM**
 Loc ID 314404 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON RD

City: RANGELY State: CO Zip: 81648

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name     | Phone        | Email                       | Comment               |
|------------------|--------------|-----------------------------|-----------------------|
| Sanford, Anita   |              | ATLX@chevron.com            |                       |
| Browning, Chuck  | 970-433-4139 | chuck.browning@state.co.us  | Field Inspector       |
| Labowskie, Steve |              | steve.labowskie@state.co.us |                       |
| Peterson, Diane  | 970-675-3842 | dlpe@chevron.com            | Regulatory Specialist |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 228668      | WELL | IJ     | 09/01/2018  | ERIW       | 103-05632 | UNION PACIFIC 4-29 | AC          |

**General Comment:**

Routine UIC inspection. Injection well inspection only.

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action |        | Date: |  |
| Type              | Main   |       |  |
| comment:          |        |       |  |
| Corrective Action |        | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                          |     |       |                 |
|--------------------------|-----|-------|-----------------|
| Type: Bradenhead         | # 1 |       | corrective date |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Deadman # & Marked | # 4 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 228668 Type: WELL API Number: 103-05632 Status: IJ Insp. Status: AC**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC RoutineInj./Tube: Pressure or inches of Hg 1660 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_

(e.g. 30 psig or -30" Hg)

Inj Zone: WEBRTC: Pressure or inches of Hg -10 Previous Test Pressure \_\_\_\_\_ Last MIT: 05/04/2018Brhd: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_Comment: Routine UIC inspection. Active injection at time of inspection. Casing blowdown 5 sec.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs   | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|-----------------|--------------------------|---------|
| Berms            | Pass            | Gravel                  | Pass                  | Self Inspection | Pass                     |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 693800647    | Inspection photos 6/18/2019 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855239">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855239</a> |