

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2019

Submitted Date:

06/19/2019

Document Number:

679704534**FIELD INSPECTION FORM**

| | | | | |
|--|--------------------------------|---|-------------------|---|
| Loc ID 315352 | Inspector Name: Moran, Rick | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 7 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested |
| Operator Information: OGCC Operator Number: <u>10539</u> Name of Operator: <u>UTAH GAS OP LTD DBA UTAH GAS CORP</u> Address: <u>1125 ESCALANTE DR</u> City: <u>RANGELY</u> State: <u>CO</u> Zip: <u>81648</u> | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

| Contact Information: | | | |
|-----------------------------|--------------|-----------------------------|---------------------------------|
| Contact Name | Phone | Email | Comment |
| Bleil, Robert | 720-425-0303 | inspections@utahgascorp.com | All inspections |

| Inspected Facilities: | | | | | | | |
|------------------------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
| 230681 | WELL | SI | 04/01/2019 | GW | 103-08349 | FEDERAL I-20-3-101-S | SI |

General Comment:

[COGCC Inspection Report Summary.](#)

On 6-19-2019 at approximately 14:15, inspector Rick Moran, conducted a routine inspection at Utah Gas well Cathedral Federal I-20-3S-101W in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Tank capacity. Photo 2. Complete by 8-16-2019.
- 2) Liner tear. Photo 3. Complete by 7-22-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704534.

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank capacity label missing. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 08/16/2019 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-693-6021

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|----------|---|----------|------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|

| | | | | | | |
|--------------------|--|---------------------|---------------------|-------------|-----------------------|------------------|
| PRODUCED WATER | 1 | <50 BBLS | Open Top | | 39.769700,-108.747700 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | 30 bbl | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Inadequate | | |
| Comment: | Tear in liner. | | | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 906.d.(1). | | | | | Date: 07/22/2019 |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 230681 | Type: | WELL | API Number: | 103-08349 | Status: | SI | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: <div>Last recorded production March 2019.</div> | | | | | | | | | |
| Corrective Action: <div></div> Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | | | | | |
| Berms | Pass | | | | | |

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 679704537 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4855324 |