

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2019

Submitted Date:

06/10/2019

Document Number:

679600966

FIELD INSPECTION FORM

Loc ID 426699 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426702	WELL	PR	02/28/2013	OW	123-34763	LEFFLER 26Q-421	PR
431514	WELL	PR	02/28/2013	OW	123-36638	Leffler 26T-421	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type			
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	TRASH		
Comment:	Trash near road of location. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/20/2019
Type	DEBRIS		
Comment:	Nest on compressor. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/20/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel (x2)		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Wire		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Methanol barrels in self containment.		
Corrective Action:		Date:	

Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLS	STEEL AST		40.539100,-104.743500
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 426702 Type: WELL API Number: 123-34763 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 431514 Type: WELL API Number: 123-36638 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: [Erosion to location near road side. See attached photos.](#)Corrective Action: [Install or reppair required BMPs per Rule 1002.f.](#)

Date: 07/10/2019

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday, June 6, 2019 at approximately 12:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at LEFFLER 26D-421, 26T-421 (PDC Energy), at .location #: 426699 in WELD COUNTY Colorado.</p> <p>While there, I observed one producing wellhead and one shut in wellhead</p> <p>During this inspection the following possible compliance issues were observed.</p> <p>1. Trash near road side of location. COMPLY WITH RULE 603.F. (Corrective Action Date: June 20, 2019) See attached photo #2 in location photos.</p> <p>2. Appears to be a birds nest on compressor. COMPLY WITH RULE 603.F. (Corrective Action Date: June 20, 2019) See attached photo #3 in location photos.</p> <p>3. Erosion occurring to location near roadside. INSTALL OR REPAIR REQUIRED BMPs PER RULE 1002.F. (Corrective Action Date: July 10, 2019) See attached photos #4, 5 in location photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report</p> <p>Continung Education Inspection.</p>	santistb	06/10/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402073512	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848647
679600967	Leffler 26Q-421	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848627
679600968	Leffler 26T-421	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848628
679600969	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848629