

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2019

Submitted Date:

06/13/2019

Document Number:

695100888

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
324505 _____ Beardslee, Tom _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 27757 #110

City: HOUSTON State: TX Zip: 77227-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Giussani, Albert	806-894-0200/806-638-1296	albert_giussani@oxy.com	Engineering Advisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211864	WELL	TA	06/08/1985	GW	055-06102	SHEEP MOUNTAIN UNIT 12-2-E	TA

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	PHOTO 1: WELLHEAD/ CURRENT OPERATOR IS NOT POSTED ON WELL SIGN.		
Corrective Action:	POST CURRENT OPERATOR ON WELL SIGN IN ACCORDANCE WITH 210 SERIES RULES. CA DATE 7/13/19.	Date:	07/13/2019

Emergency Contact Number:	
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
Date:	<input type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:		corrective date
Type: Bradenhead	# 1	
Comment:	IS PLUMBED TO SURFACE	
Corrective Action:		Date:

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211864 Type: WELL API Number: 055-06102 Status: TA Insp. Status: TA

Workover

Comment: MIT PSI 350, PRESSURE HELD AT 350 DURING TEST. PERF 6310'-6354' CIBP SET AT 6265'

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402074851	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849780
695100889	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849778