

# Inspection Photos

API: 05-071-09060

Operator: ARP PRODUCTION COMPANY  
WAPITI OPERATING LLC

Inspection Date: 6/19/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09060 | Date: 6/19/2019

## Inspection Photos



**Photo 1.** The culvert along the main access road has filled in with sediment.  
Lat/Long:37.02576,-104.83253



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09060 | Date: 6/19/2019

## Inspection Photos



**Photo 2.** There is erosion down the side of the road. No BMPs installed to prevent erosion. Lat/Long:37.02576,-104.83253



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09060 | Date: 6/19/2019

## Inspection Photos



**Photo 4.** There is List B noxious weeds growing along the main & access road to the location. (Musk thistle shown in photo)



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09060 | Date: 6/19/2019

## Inspection Photos



**Photo 5.** No LO/TO on pipe riser.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09060 | Date: 6/19/2019

## Inspection Photos



**Photo 6.** Well sign is present. Operator name on sign has not changed yet.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09060 | Date: 6/19/2019