

Inspection Photos

API: 05-071-06867

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 6/19/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 6/19/2019

Inspection Photos



Photo 1. There is List B noxious weeds growing along the access road near the building near the location. (Canada thistle shown in photo)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 6/19/2019

Inspection Photos



Photo 2. Facing toward the location. Vegetation has not established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 6/19/2019

Inspection Photos



Photo 3. Wattles were installed. There was no sign of seeding or germination in area. Erosion may have washed away seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 6/19/2019

Inspection Photos



Photo 4. Wattles have been installed however stormwater is flowing underneath wattles.,



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 6/19/2019

Inspection Photos



Photo 5. There are sign stormwater is flowing underneath the wattle. Wattles were not properly trenched into the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06867 | Date: 6/19/2019