

Inspection Photos
Location Name: Baierl Fee 3
API: 05-107-06048



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Stained soil at wellhead with fresh gravel on top. Rag stopping apparent slow leak.

Inspection Photos
Location Name: Baierl Fee 3
API: 05-107-06048



Photo 3. Close-up of rag and apparent slow leak from Photo 2.



Photo 4. Pit.