

Inspection Photos
Location Name: Mary Hite Fee 1
API: 05-107-06013



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: Mary Hite Fee 1
API: 05-107-06013



Photo 2. Stained soil at wellhead with fresh gravel on top. Rag stopping apparent slow leak.



Photo 3. Close-up of photo 2.