

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2019

Submitted Date:

06/20/2019

Document Number:

693700200**FIELD INSPECTION FORM**Loc ID 422622 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                | Comment                         |
|--------------|-------|----------------------|---------------------------------|
|              |       | EHSRC@bonanzacrk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type                | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|---------------------|--------|-------------|------------|-----------|-----------------|-------------|
| 422621      | WELL                | SI     | 02/01/2019  | OW         | 123-33328 | Cass 7-62 15-1H | EI          |
| 465524      | SPILL OR<br>RELEASE | AC     | 06/20/2019  |            | -         | Cass 7-62-15-1H | EI          |

**General Comment:**

| Inspected Facilities |        |       |          |             |           |         |    |               |    |
|----------------------|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 422621 | Type: | WELL     | API Number: | 123-33328 | Status: | SI | Insp. Status: | EI |
|                      |        |       |          |             |           |         |    |               |    |
| Facility ID:         | 465524 | Type: | SPILL OR | API Number: | -         | Status: | AC | Insp. Status: | EI |
|                      |        |       |          |             |           |         |    |               |    |

**Environmental****Spill/Remediation:**

Comment: [COGCC inspection of spill reported by Operator on 6/19/2019. Operator is investigating extent and source of impacts and will provide results of investigation on Form 19 Supplemental Report.](#)

Corrective  
Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                      | URL   |
|--------------|----------------------------------|---|
| 693700201    | Cass 7-62 15-1H Photos 6-20-2019 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4856764">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4856764</a> |