

Inspection Photos
Location Name: ROADSTER 11-34 TR
API#: 05-071-07611
INSP. #: 695100923



PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: ROADSTER 11-34 TR

API#: 05-071-07611

INSP. #: 695100923



PHOTO 3: AREA OF IMPACTED GRAVEL APP. 7' ROUND NEAR WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/19/19

PHOTO 4: AREA OF IMPACTED GRAVEL APP. 5' ROUND NEAR METERHOUSE. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/19/19

Inspection Photos
Location Name: ROADSTER 11-34 TR
API#: 05-071-07611
INSP. #: 695100923



PHOTO 5: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 7/4/19.