

Inspection Photos

Location Name: BURRO CANYON 13-28 FOLLOWUP

API#: 05-071-06113

INSP. #: 695100925



Colorado Oil & Gas Conservation Commission
37.22859, -104.79241, 2227.0m, 256°
2019/06/19 15:27:55



Colorado Oil & Gas Conservation Commission
37.22852, -104.79227, 2240.0m, 242°
2019/06/19 15:28:58

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: BURRO CANYON 13-28 FOLLOWUP

API#: 05-071-06113

INSP. #: 695100925



PHOTO 3: APP. 10' BY 5' AREA OF IMPACTED SOIL BETWEEN WELLHEAD AND COMPRESSOR APPEARS TO BE FROM DRAINING TWO DIFFERENT DRAINS HIGHLIGHTED BY ARROWS ON PHOTO. IMMEDIATELY STOP DUMPING DRAINS ON LOCATION AND Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/21/19.

PHOTO 4: UNUSED EQUIPMENT THAT WAS NOTED IN PREVIOUS INSPECTION (DOC# 688400098) WAS NOT ADDRESSED. IMMEDIATELY REMOVE UNUSED EQUIPMENT IN ACCORDANCE WITH RULE 603.f. CA DATE IMMEDIATELY.

Inspection Photos
Location Name: BURRO CANYON 13-28 FOLLOWUP
API#: 05-071-06113
INSP. #: 695100925



**PHOTO 5: Vacuum pump observed on well without COGCC approval.
Provide COGCC with documentation showing approval of use of
vacuum pump. CA DATE 7/6/19.**