

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2019

Submitted Date:

06/21/2019

Document Number:

679704575

FIELD INSPECTION FORM

Loc ID 316555 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10560
Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME
Address: PO BOX 2326
City: VICTORIA State: TX Zip: 77902

Findings:

- 13 Number of Comments
- 10 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Hahn, Mike	361-570-1600 X24	mhahn@xeogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285932	WELL	SI	08/01/2017	GW	103-10835	HELLS HOLE 19-1	SI

General Comment:

[COGCC Inspection Report Summary.](#)

On 6-20-2019 at approximately 15:45, inspector Rick Moran, conducted a routine well inspection at Extreme Energy well Hells Hole 19-1 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Well head sign. Photo 14. Complete by 7-22-2019.
- 2) Battery sign. Photo 5. Complete by 7-22-2019.
- 3) Tank label. Photo 6. Complete by 7-22-2019.
- 4) Emergency contact number. Photo 5. Complete by 7-22-2019.
- 5) Unused barrel. Photo 13. Complete by 7-22-2019.
- 6) Weeds. Photo 3, 8, 9, 10. Complete by 7-8-2019.
- 7) Oily waste. Photo 12. Complete by 7-22-2019.
- 8) Bird protection. Photo 3. Complete by 7-22-2019.
- 9) Tank battery berm. Photo 7, 8. Complete by 7-22-2019.
- 10) Ditch hill side of tank battery. Photo 7. Complete by 7-22-2019.
- 11) MIT

Note: The well had never been inspected by the COGCC.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704575.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	No sign present at well head.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	07/22/2019
Type	BATTERY		
Comment:	Sign is the previous operator.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	07/22/2019
Type	TANK LABELS/PLACARDS		
Comment:	Sign on one tank is illegible. No sign exists on the other tank.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/22/2019

Emergency Contact Number:			
Comment:	No emergency contact phone number on sign.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	07/22/2019

Good Housekeeping:			
Type	OTHER		
Comment:	Oily waste on ground next to broken oil container.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	07/22/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused barrel next to pump jack.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/22/2019
Type	WEEDS		
Comment:	Weeds next to separator, meter building, well head, and on tank battery berm.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/08/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel wall around pump jack.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 0		
Comment:	No bird cone or netting on separator vent pipe.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: 07/08/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		39.864100,-108.992100
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate
Comment:	Inadequate berms around tank(s). Berms breached from storm water.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 07/22/2019

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 285932 Type: WELL API Number: 103-10835 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Casing gage pressure @ 200 psi. Tubing pressure gage @ 0 psi.
No current MIT on record or delinquent as required by Rule 326

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Fail					
Berms	Fail					

Comment: Berm and ditch on uphill side of tank battery is breached through which storm water is flowing into the tank battery bermed area.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/22/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704576	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4857742