

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2019

Submitted Date:

06/21/2019

Document Number:

689802812

**FIELD INSPECTION FORM**

Loc ID 313077 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10407  
Name of Operator: ANTLER ENERGY LLC  
Address: PO BOX 104  
City: BAGGS State: WY Zip: 82321

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150427	UIC DISPOSAL	AC	03/03/1999		-	SAND HILLS FEDERAL #14-15	SI

**General Comment:**

[COGCC Inspection Report 689802812 Summary](#)  
On Tuesday 6/18/2019 at approximately 9:30, I, Inspector Emily Waldron, conducted a field inspection at Antler Energy LLC Sand Hills Federal 14-15, at 081-06896 in Moffat County Colorado. While there, I witnessed a 5 year UIC MIT. This is a summary of inspection report 689802812.

**Inspected Facilities**

Facility ID: 150427 Type: UIC API Number: - Status: AC Insp. Status: SI

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: _____
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: _____
			AnnMTReq: _____

Comment:

Corrective Action:  Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: 5 Year Tbg psi: 0 Csg psi: 525 BH psi: \_\_\_\_\_

Insp. Status: Pass

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802826	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4857746">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4857746</a>