

Inspection Photos

Location Name: LORENCITO 3-22-34-66

API#: 05-071-06662

INSP. #: 695100931



PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: LORENCITO 3-22-34-66

API#: 05-071-06662

INSP. #: 695100931



PHOTO 3: PRODUCED WATER TANK IS FULL AND IS RUNNING OVER INTO SECONDARY CONTAINMENT SPOKE WITH JACK WISEMAN BY PHONE TO HAVE FLUID LEVEL LOWERED. LOWER FLUID LEVEL PER RULE 902.b. Control and contain spills/releases and clean up per Rule 906.a. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff. CA DATE 6/21/19.

PHOTO 4: INADEQUATE MATERIAL AND COMPACTION USED IN BERM CONSTRUCTION. USE ADEQUATE MATERIAL WITH SUFFICIENT COMPACTION TO PREVENT FLUID FROM MIGRATING THROUGH BERMS. Repair or install berms or other secondary containment devices per Rule 906.d.(1). CA DATE 7/21/19.

Inspection Photos

Location Name: LORENCITO 3-22-34-66

API#: 05-071-06662

INSP. #: 695100931



PHOTO 5. PHOTO SHOWING PRODUCED WATER TRAVELING DOWN DRAINAGE DITCH APP. 120' FROM BACK OF TANK. LOWER FLUID LEVEL PER RULE 902.b. Control and contain spills/releases and clean up per Rule 906.a. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff. CA DATE 6/21/19.

PHOTO 6: NO NFPA STICKER POSTED ON PRODUCED WATER TANK. ALSO CAPACITY OF TANK IS NOT POSTED. COMPLY WITH RULE 210. d.

Inspection Photos

Location Name: LORENCITO 3-22-34-66

API#: 05-071-06662

INSP. #: 695100931



PHOTO 7: GUY LINE ANCHOR NOT MARKED. INSTALL GUY LINE MARKER IN ACCORDANCE WITH RULE 1003.a.

PHOTO 8: UNUSED EQUIPMENT STORED ON LOCATION. REMOVE UNUSED EQUIPMENT IN ACCORDANCE WITH RULE 603.f. CA DATE 7/21/19