

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/21/2019

Submitted Date:

06/21/2019

Document Number:

688304903**FIELD INSPECTION FORM**
 Loc ID 309596 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10691Name of Operator: PHOENIX RESOURCES LLCAddress: 5566 S SYCAMORE STREETCity: LITTLETON State: CO Zip: 80120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heffner, Taylor	303-219-3362	theffner@phxresources.com	
Burn, Diana		diana.burn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218136	WELL	DM	06/07/1993	GW	073-06121	NEWBY 6-12	DM

**General Comment:**

MIT Inspection, failed on domestic gas well to be converted to TA status well per COGCC Engineering.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-219-3362

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	steel panels in pasture		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 218136 Type: WELL API Number: 073-06121 Status: DM Insp. Status: DM**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Failed Form 21 is attached. Low pressure gas returned to truck tank for about 20 minutes. One-hundred-thirty BBLs of water used to load hole but did not load hole. Casing was on vacuum after taking hose off.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.Date: 07/05/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304976	Phoenix Resources Newby 6-12 Form 21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858249">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858249</a>
688304977	Phoenix Resources Newby 6-12 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858250">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858250</a>
688304978	Phoenix Resources Newby 6-12 wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858251">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858251</a>
688304979	Phoenix Resources Newby 6-12 contractors	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858252">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858252</a>