

Inspection Photos
Operator: BP America
Location/API #: 067-06285
Date: 6-11-2019



Photo 1. View of the southern project area from the southwestern corner facing eastward.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of head-cut erosion and erosional channeling downstream from culvert outlet along the access road. This appears to be a result of concentrated stormwater flows exiting the culvert.