

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2019

Submitted Date:

06/24/2019

Document Number:

693200356

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
424630 \_\_\_\_\_ Murray, Richard \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Heil, John		john.heil@state.co.us	
Arauzo, Steven		steven.arauza@state.co.us	West Environmental Protection Specialist
Caerus		COGCC.inspections@caerusoilandgas.com	All Piceance inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
464596	SPILL OR RELEASE	AC	05/23/2019		-	8512E flowline release	EG

**General Comment:**

COGCC joint inspection with EPS S. Arauzo, EPS J. Heil and Western Integrity Inspector R. Murray  
Engineering Integrity Inspection performed on June 20, 2019. In response to initial form 19 spill report Doc # 402046587

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type					corrective date
Other	# 2				
Comment:	Rat hole protectors, weld plates have come lose, repairs needed, see photo log				
Corrective Action:	Repair or replace rat hole covers				Date: 07/29/2019

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 464596 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

**Flowline**

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: No Age: 1-5 Yrs Contents: Produced Water

Integrity Summary

Failures: Other Spills: Yes Repairs Made: Yes  
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: No Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Establish root cause of the failure and submit a flowline pressure test that was performed before returning to service via Form 4

Corrective Action:

Date: 07/03/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200357	424630	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858545">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858545</a>