

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2019

Submitted Date:

06/17/2019

Document Number:

687904904**FIELD INSPECTION FORM**
 Loc ID 333612 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159068	UIC DISPOSAL	AC	09/13/2001		-	SITTON DISPOSAL 1	AC
159077	UIC DISPOSAL	AC	09/13/2001		-	SITTON WATER DISPOSAL #2	AC

General Comment:[Site inspection with photos at the end of this report. Conducted MIT test of UIC injection wellhead.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on tanks have no fire hazard number for produced water and need to be updated.		
Corrective Action:	Comply with Rule 210.b.	Date:	07/17/2019
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency contact information posted on signs.		
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:	Orange safety fencing partially buried along East side of 100bbl tank berm.		
Corrective Action:	Remove trash per Rule 603.f.	Date:	06/27/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Chain link privacy fence around location.		
Corrective Action:		Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	Injection well pumping equipment in metal building.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	MCC for electric driven pumps.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Injection wellheads.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Type: Flow Line	# 4	
Comment:	Flowline from outlet of injection pumping equipment to wellhead. Inlet piping from gathering system to tanks on location. 1" flowline for heated steel tank fuel gas.	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	Plumbed to surface in PVC tube.	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:	On heated tanks.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	1000 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Insufficient	Base Sufficient	Adequate
Comment:	Northern and western walls inside secondary containment, liner has came loose and is not mounted to the wall.			
Corrective Action:	Repair secondary containment per Rule 906.d.(1)			Date: 07/17/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 159068 Type: UIC API Number: - Status: AC Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: 1600

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: _____
 TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: _____
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: 5 Year Tbg psi: 1225 Csg psi: 1.7 BH psi: 0.0

Insp. Status: Pass

Comment: Conducted MIT test on well. Last 5 year MIT completed in 6/19/2014 (Doc# 200407773).
-Start pressure 1600psig
-@5min: 1590psig, @10min: 1580psig, @15min: 1580psig, @20min: 1580psig, @30min:
1580psig final.

Corrective Action: _____ Date: _____

Facility ID: 159077 Type: UIC API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					
Compaction	Pass	Gravel	Pass			
Ditches	Pass					
Waddles	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402078067	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852357
687904905	Tank Labeling produced water fire hazard.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852346
687904906	Trash.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852347
687904907	Secondary containment liner.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852348
687904908	Secondary containment liner.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852349