

**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**EWS #4 TB Facility. Looking north.**




**North side building showing tank damage. All 28 FG tanks damaged/destroyed. 5 steel tanks (oil) undamaged. Photo looking east.**

**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**North side building showing tank damage. All 28 FG tanks damaged/destroyed. Crews cleaning out tanks in preparation for removal. Photo looking north.**



**North side building showing tank damage. Photo looking north.**

**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Damaged tanks. Tank on left same tank as in previous photograph. Photo looking east from off-loading area.**



**Looking south from north side of TB.**



**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Damaged tanks. North end of TB. Photo looking west.**



**Damaged tanks. North end of TB. Photo looking south.**

**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Northwest end of TB showing little or no tank damage. Note stained area north of TB. Photo looking southwest**



**Oil stained area north of TB.**



**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Northwest end of TB showing undamaged tanks. Photo looking south.**



**West side of TB showing undamaged tanks. Photo looking southeast.**

**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Fluid collection area west of TB (storm water control ditch). Note staining. Photo looking south**



**Storm water control ditch. Note staining. Photo looking north.**



**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Storm water ditch looking to south from location in previous photo. Note staining.**



**Storm water ditch northeast side of facility. GW monitoring location. Ditch passes under road through culvert to east side. Note staining. Photo looking south west.**



**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Storm water ditch passes under road through culvert to east side. Note staining. Photo looking north.**



**Storm water ditch east side. Note staining. Photo looking north.**



**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Detail showing oily fluid in storm water ditch eastern side of facility.**



**Storm water ditch on east side of facility. Crew removing fluids from ditch. Photo looking south.**



**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Fluid removal from storm water ditch.**



**Storm water retention pond on southeast side of facility. Photo looking south east.**

**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Storm water retention pond. Photo looking south.**



**Western end of retention pond. Photo looking southwest.**



**Inspection Photos: June 24, 2019**  
**Location Name: EWS #4 Tank Facility – Lightning Strike/Fire**  
**SWSW Section 17 – Township 2 North - Range 63 West**  
**Weld County**



**Storm water retention pond from east side looking to west. No sheen or floating oil observed. Photo looking west.**



**East side of storm water retention pond. Note stained vegetation. Photo looking south.**