

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2019

Submitted Date:

06/24/2019

Document Number:

679704590

**FIELD INSPECTION FORM**

Loc ID 315252 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Maralex	970-858-8550	aak@gvep.net	
Graves, Jim	970-712-0099	mrinc20@qwestoffice.net	Operations Manager
Reid, Jordan	970-563-4000	maralextechjr@gmail.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230491	WELL	SI	01/01/2012	GW	103-08158	TRAIL CANYON-FEDERAL 1-2	SI

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 6/24/2019 at approximately 9:45, inspector Rick Moran, conducted a follow up inspection at Maralex Resources well Trail Canyon Federal 1-2 in Rio Blanco county of FIR document 679704236.

During this inspection the following were identified as resolved :

- 1) Uncapped riser.

The following compliance issues were observed as uncompleted:

- 1) MIT.

This is a summary of inspection report 679704590.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	970-858-8550		
Corrective Action:			Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

		#			corrective date
Type: Gas Meter Run		# 1			
Comment:					
Corrective Action:					Date:
Type: Bird Protectors		# 1			
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator		# 1			
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked		# 4			
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 230491 Type: WELL API Number: 103-08158 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No current MIT on record or delinquent as required by Rule 326.  
Last recorded production December 2011. No MIT on file.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion channel on the north edge of the location going into the creek.  
The P&A marker for well Trail Canyon 1-2A is located 11 ft from the edge of the erosion channel.

Corrective Action:  Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704591	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859753">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859753</a>