

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2019

Submitted Date:

06/21/2019

Document Number:

689802842**FIELD INSPECTION FORM**Loc ID 313060 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 97810Name of Operator: EOG Y RESOURCES INCAddress: 105 SOUTH 4TH STCity: ARTESIA State: NM Zip: 88210**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Elgin, Jerry		jelgin@mspartners.com	
Allman, Stephanie	307-382-4005	stephanie_allman@eogresources.com	
Gallenbeck, Danny		dgallenbeck@ctfieldsvcs.com	
Blaylock, Connie		cblaylock@mspartners.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223491	WELL	SI	07/01/2018	GW	081-06857	PEPPLER FEE COM 12-18	TA

General Comment:

COGCC Inspection Report 689802842 Summary

On Tuesday 6/11/2019 at approximately 10:45, I, Inspector Emily Waldron, conducted a field inspection at EOG Y Resources Inc Peppler Fee Com 12-18 at 05-081-06857 in Moffat County Colorado.

While there, I observed a temporarily abandoned well.

During this inspection the following possible compliance issues were observed:

Tubing and other debris remains in tank battery area. See photo 4. Comply with Rule 603.f by 7/22/2019.

3 - 3" steel risers at 40.99715, -107.65801 and 1 - 2" steel riser in tank battery at 40.99719, -107.65719. Flowline risers not LO/TO or marked are considered unused equipment. See photos 3 and 5. Comply with Rule 603.f by 6/24/2019.

Non-reportable spill - stained soil in tank battery. See photo 5. Comply with Rule 603.f by 7/22/2019.

Well TA, wellhead LOTO. No Form 4 TA Annual report on file.

Form 10 document number 2304077, submitted 1/23/2019, On Hold to transfer from EOG Y Resources Inc. to Southland Royalty Company, LLC.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689802842.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	307-324-2658		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Non-reportable spill - stained soil in tank battery.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/22/2019
Type	DEBRIS		
Comment:	Tubing and other debris remains in tank battery area.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/22/2019
Type	UNUSED EQUIPMENT		
Comment:	3 - 3" steel risers at 40.99715, -107.65801 and 1 - 2" steel riser in tank battery at 40.99719, -107.65719. Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/24/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	223491	Type:	WELL	API Number:	081-06857	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: _____									
Comment: Well TA, wellhead LOTO. No Form 4 TA Annual report on file.									
Corrective Action: _____									
Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802843	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861111