

Inspection Photos

API: 05-017-07453

Operator: RESOURCE DEVELOPMENT

Inspection Date: 6/21/2019

Inspection Photos



Photo 1. Facing west along the former access road. There is weedy areas along the road.

Inspection Photos



Photo 2. View of vegetation along the road. There was Field bindweed and Kochia along the road which was not found in the adjacent pasture.

Inspection Photos



Photo 3. Facing west at the location. There is areas with no vegetation growth and possible soil compaction.

Inspection Photos



Photo 4. Facing east at the location. There is areas with no vegetation growth and possible soil compaction.

Inspection Photos



Photo 5. This area approximately 100'x20' has minimal desirable vegetation growth.

Inspection Photos



Photo 6. Facing west at the surrounding undisturbed pasture.

Inspection Photos



Photo 7. Transect on location facing NW.



Photo 8. Transect on location facing SE.

Inspection Photos



Photo 9. Transect Reference facing SE.



Photo 10. Transect Reference facing NW.

Inspection Photos

Cover Data Date: 6/21/2019 Inspected By: Ryan Costa
 Location/Operator: APS # 017-07453 Resource Development

Transect #/disturbed/Ref	Disturbed	Reference						
Transect Orientation and first photo, degrees	38.35 004 -102.39570	NW	38.31991 -102.39507	SE				
Photo Midpoint (2)								
End transect	38.35016 -102.39602	SE	38.31991 -102.39461	NW				
Photo other								
Aspect/Slope	Flat		Flat					
		Totals		Totals		Totals		Totals
Cryptogams (eg. Moss, lichen)								
Litter	26		46					
Bare Soil	46		12					
Rock								
Total Weeds	5							
Total Desirable Species	29		42					
80% Check	29/42 = 69%							
	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P
Kochia sp.	1	2						
Spo. cry	1	2						
Field bindweed	1	2						
Hal. ann.	1	2						
Row sp.	1	2						
Bl. off	1	2						
Ans. sm.	1	2						

06-28-2019

2nd= second hit; P= plant species present but not hit

Photo 11. Transect Data