

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	unused equipment in motor house, and on location see pic 2,3,4,5,6,7,8		
Corrective Action:	Comply with Rule 603.f .	Date:	11/26/2018
Type			
Comment:	stained soil in motor house see pic 4		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	07/26/2019

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	4' barb wire		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	electric boxes/automation		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202545 Type: WELL API Number: 001-07950 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 6/26/19 at approximately 1000 I, Inspector Justin Medina conducted an on-site inspection at P3- API 001-07950 -Hosmer 21-3218 in Adams County Colorado. While there, I observed Shut in well This is a follow up inspection from document # 688401166 Corrective Actions are Delinquent During this inspection the following possible compliance issues were observed: unused equipment in motor house, and on location see pic 2,3,4,5,6,7,8 Comply with Rule 603.f . 11/26/19 stained soil in motor house see pic 4 Properly treat or dispose of oily waste in accordance with 907.e 7/26/19 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	06/26/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101220	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862603