

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

06/26/2019

Document Number:

687905030

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325920 \_\_\_\_\_ Stewart, Joseph \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone        | Email                       | Comment                               |
|------------------|--------------|-----------------------------|---------------------------------------|
| Inspections, All |              | SanJuanCOGCC@bp.com         | <a href="#">All Inspections</a>       |
| Beebe, Sabre     | 970-779-9398 | Sabre.Beebe@bpx.com         | <a href="#">SW Inspection Reports</a> |
| Labowskie, Steve |              | steve.labowskie@state.co.us |                                       |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 215569      | WELL | PR     | 12/03/1988  | GW         | 067-07174 | CUNDIFF FEDERAL B 1 | PR          |

**General Comment:**

[Site inspection with photos at the end of this report](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |                                      |       |  |
|--------------------|--------------------------------------|-------|--|
| Type               | WELLHEAD                             |       |  |
| Comment:           | Sign posted at entrance to location. |       |  |
| Corrective Action: |                                      | Date: |  |

Emergency Contact Number:

|                    |                                     |       |  |
|--------------------|-------------------------------------|-------|--|
| Comment:           | Contact information posted on sign. | Date: |  |
| Corrective Action: |                                     |       |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | SEPARATOR                                       |       |  |
| Comment:           | Cattle panels around separator and meter house. |       |  |
| Corrective Action: |   | Date: |  |
| Type               | WELLHEAD  |       |  |
| Comment:           | Cattle panels around wellhead.                  |       |  |
| Corrective Action: |   | Date: |  |

**Equipment:**

| Type                            |  |       | corrective date |
|---------------------------------|--|-------|-----------------|
| Type: Flow Line                 | # 4  |       |                 |
| Comment:                        | 1-2" flowline from wellhead to separator. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to offsite dogleg. |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Pump Jack                 | # 1  |       |                 |
| Comment:                        | Linear rod pump.   |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Vertical Heated Separator | # 1  |       |                 |
| Comment:                        |  |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Ancillary equipment       | # 1  |       |                 |
| Comment:                        | Wellhead.  |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Gas Meter Run             | # 1  |       |                 |
| Comment:                        |  |       |                 |
| Corrective Action:              |  | Date: |                 |

|                       |                        |       |  |
|-----------------------|------------------------|-------|--|
| Type: Bradenhead      | # 1                    |       |  |
| Comment:              | PVC bradenhead access. |       |  |
| Corrective Action:    |                        | Date: |  |
| Type: Bird Protectors | # 1                    |       |  |
| Comment:              | On separator stack.    |       |  |
| Corrective Action:    |                        | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 215569 Type: WELL API Number: 067-07174 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel            | Pass            |                         |                       |               |                          |         |
| Compaction        | Pass            | Compaction              | Pass                  |               |                          |         |
| Berms             | Pass            | Culverts                | Pass                  |               |                          |         |
| Gradient Terraces | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 687905031    | Location    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862620">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862620</a> |