

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

06/26/2019

Document Number:

696101057

FIELD INSPECTION FORM

Loc ID 306472 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288978	WELL	SI	05/01/2014	OW	123-24722	HAGEMIESTER 43-6	TA
447071	TANK BATTERY	AC	07/29/2016		-	HAGERMIESTER-66N63W 6NESE	IO

General Comment:

This is a WELL & BATTERY inspection.
Well is Temporarily Abandoned | TA.
Battery: Abandoned, ALL equipment removed.
Reclamation progressing.
Abandoned Centralized Battery formerly served 2 Location IDs (306472, 310482).
(2 - wells ; Temporarily Abandoned | TA).
Abandoned Battery GPS Coordinates SE Corner: 40.514442, -104.471998
Follow-up to Field Inspection Report Doc. #684905453 dated 05/24/2018.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Removed. Battery Abandoned.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Removed. Battery Abandoned.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	<p>Prior insp: Stained soil at gas meter run. Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil at gas meter run. Comply w/ Rule 605.d. Original Corrective Action date: 06/25/2018.</p> <p>This insp: * Battery has been abandoned. ALL equipment has been removed. Stained soil NOW appears mitigated. See photos #3, 4.</p>		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Removed. Battery Abandoned.		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Removed. Battery Abandoned.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Removed. Battery Abandoned.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 0		
Comment:	Removed. Battery Abandoned.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Removed. Battery Abandoned.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Removed. Battery Abandoned.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Removed. Battery Abandoned.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.514442,-104.471998
Comment:	Abandoned Centralized Battery formerly served 2 Location IDs (306472, 310482). Abandoned Battery GPS Coordinates SE Corner: 40.514442, -104.471998				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0	300 BBLs	STEEL AST			
Comment: Removed. Battery Abandoned.						
Corrective Action:				Date:		

Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0	100 BBLs	PBV FIBERGLASS			
Comment: Removed. Battery Abandoned.						
Corrective Action:				Date:		

Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		

Venting:						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		

Flaring:						
Type						
Comment:						

Corrective Action:	Date:
--------------------	-------

--

Inspected Facilities

Facility ID: 288978 Type: WELL API Number: 123-24722 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Battery Abandoned. ALL equipment removed.
Last Prod: 04/2014.
SI/TA. MIT requirement waived per variance Doc #401474555. Orange decommission tag for SI/TA status present. Locked Out Tagged Out (LOTO). (NOBLE)

Corrective Action: Date:

Facility ID: 447071 Type: TANK API Number: - Status: AC Insp. Status: IO

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: **Prior insp:**
 Stormwater erosion on SW side of location.
 Refer to Rule 1002.f.
 Install or repair required BMPs. Comply w/ Rule 1002.f.
 Original Corrective Action date: 06/25/2018.

This insp:
 * Battery has been abandoned.
 Stormwater erosion on SW side of location NOW appears mitigated
 See photos #5, 6.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 06/26/2019 at approximately 13:59 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: HAGERMIESTER-66N63W /6NESE Location ID: 306472 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s) - 1: Temporarily Abandoned TA. Battery: Abandoned, ALL equipment removed. Reclamation progressing. Abandoned Centralized Battery formerly served 2 Location IDs (306472, 310482). Abandoned Battery GPS Coordinates SE Corner: 40.514442, -104.471998</p> <p>Follow-up to Field Inspection Report Doc. #684905453 dated 05/24/2018. 2 of 2 Corrective Actions appears addressed. 1.) Stained soil at gas meter run. Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil at gas meter run. Comply w/ Rule 605.d. Original Corrective Action date: 06/25/2018. * Battery has been abandoned. ALL equipment has been removed. Stained soil NOW appears mitigated. See photos #3, 4.</p> <p>2.) Stormwater erosion on SW side of location. Refer to Rule 1002.f. Install or repair required BMPs. Comply w/ Rule 1002.f. Original Corrective Action date: 06/25/2018. * Battery has been abandoned. Stormwater erosion on SW side of location NOW appears mitigated See photos #5, 6.</p> <p>NO: NEW Corrective Actions observed on this inspection.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/26/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101058	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862699