



FOR OGCC USE ONLY

Date Received: 10/3/2001
Doc Num: 900732

WELL ABANDONMENT REPORT

Submit original plus one copy. This form is to be submitted as an intent whenever a plugging is planned on a borehole. The approved intent shall be valid for six (6) months after the approval date; after that period a new intent will be required. After the plugging is complete, this form and one copy shall again be submitted along with third party cement verification as a subsequent report of the work as actually completed.

OGCC Operator Number: 6495	Contact Name and Telephone	24-hour Contact (required)
Name of Operator: BARRETT RESOURCES CORP	MARY BEGANO	
Address: TOWER 3 SUITE 1000 1515 A	Phone: 303 572-3900	
City: DENVER State: CO Zip: 80202	Fax: 303 629-8265	Tel:

API Number: 05-071-07415 00	OGCC Lease No.:	Other wells in this lease?
Well Name: APACHE CANYON	Well Number: 13-12V	
Location (QtrQtr, Sec, Twp, Rng, Mer): NWSW Sec 13 T 34S R 68W PM 6		
County: LAS ANIMAS	Federal, Indian, or State Lease Number:	
Field Name: APACHE CANYON	Field Number: 2818	

Attachment Checklist	Doc Num

Notice of Intent to Abandon

Only Complete the Following Background Information for Intent to Abandon

Reason for Abandonment: MECH. PROB

Casing to Be Pulled: _____ Top of Casing Cement: 0

Fish in Hole: Yes

Wellbore has Uncemented Casing Leaks: No

Details: RBP STUCK AT 1684'. CALLED FOR PLUGGING INSTRUCTIONS IF RBP CAN NOT BE RETRIEVED.

Current and Previously Abandoned Zones

Formation code	Perf Top	Perf Bottom	Date Abandoned	Method of Isolation	Plug Depth
VRMJ <u>VRMJ</u>				BRIDGE PLUG	1993
VRMJ <u>VRMJ</u>				BRIDGE PLUG	2040
VRMJ	1856	2069		NONE	

Casing History

Casing String	Casing Size	Casing Depth	Cement Top	Stage Cement Top
SURF	8 5/8	211	0	
1ST	5 1/2	2256	0	

Plugging Procedure for Intent and Subsequent Report

CIBP # 1: Depth 2040 ft. with 0 sacks cement on top.

CIBP # 2: Depth 1993 ft. with 0 sacks cement on top.

Set 20 sacks cement from 1600 ft. to 1500 ft. in CASING

Set 20 sacks cement from 260 ft. to 160 ft. in CASING

Set 10 sacks at surface.

Cut all casing strings four feet below ground level, weld on plate

Set _____ sacks in rat hole. Set _____ sacks in mouse hole.

NOTE: Two(2) sacks cement required on all CIBPs.

Dry-Hole Marker :

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing.	Plugging Date:
*Wireline Contractor:	*Cementing Contractor:
Type of Cement and Additives Used:	

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: MARY BEGANO

Signed?

Title: OFFICE MANAGER

Date: 10/3/2001

OGCC Approved: DIMATTEE

Title:

Date: 10/3/2001

CONDITIONS OF APPROVAL, IF ANY:

719-868-2714

Attn
Mary

Beggs

NWSW 13 34S 68W

WILLIAMS PRODUCTION

AC 13-12V

API # 071-07415-00

plugging procedure

Can not get
anything past
this point. →

