

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

06/26/2019

Document Number:

679601049

FIELD INSPECTION FORM

Loc ID 336628 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SRC ENERGY INC
Address: 1675 BROADWAY SUITE 2600
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		cogccinspections@srcenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250310	WELL	PR	11/29/2000	GW	123-18113	SYLVESTER 36-16H6	PR
250354	WELL	PR	12/18/2009	GW	123-18157	SYLVESTER 1-116	PR
421975	WELL	PR	10/09/2012	GW	123-33120	SYLVESTER G 06-30D	PR

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Adequate (x3)		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
	Comment: Panel (x3)		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Bradenhead	# 3				
Comment:	<input style="width: 95%;" type="text"/>				
Corrective Action:		Date:			
Type: Plunger Lift	# 3				
Comment:	<input style="width: 95%;" type="text"/>				
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:

Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 250310 Type: WELL API Number: 123-18113 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 250354 Type: WELL API Number: 123-18157 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 421975 Type: WELL API Number: 123-33120 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
No corrective actions observed at the time of inspection.	santistb	06/26/2019
Continuing Inspection Education.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601050	Sylvester 1-1HI6	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864259
679601051	Sylvester 36-16H6	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864260
679601052	Sylvester G 06-30D	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864261