

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

06/27/2019

Document Number:

679704625

**FIELD INSPECTION FORM**

Loc ID 396671 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 27900  
Name of Operator: EQUITY OIL CO  
Address: 1700 BROADWAY STE 2300  
City: DENVER State: CO Zip: 80290-

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Tobin, Polly		pollyt@whiting.com	
Thompson, Bud		BLThomps@BLM.gov	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228223	WELL	PA	05/31/1957	DA	103-05041	SULPHUR FALLS GOV'T 1-A	PA

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 6-26-2019 at approximately 14:00, inspector Rick Moran, conducted a routine well inspection at Equity Oil well South Sulphur 1 in Rio Blanco county.

P&A well is venting gas.

This is a summary of inspection report 679704625.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	P&A marker.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	YES		
Comment:	Well is venting gas through pin holes in welds on top of P&A marker. A 3 cubic foot bag filled with gas in 27 minutes.		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 228223 Type: WELL API Number: 103-05041 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704626	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864278">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864278</a>