

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2019

Submitted Date:

06/20/2019

Document Number:

687904952**FIELD INSPECTION FORM**Loc ID 333826 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|-----------------------------|------------------------------------|
| Roland, Kandis | | kroland@hilcorp.com | |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Ray, Mandi | 505-324-5122 | mray@hilcorp.com | |
| Shorty, Priscilla | | pshorty@hilcorp.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 258094 | WELL | PR | 12/27/2000 | GW | 067-08322 | ARGENTA 33-10 4-3 | PR |

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☐

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Missing tank labels/placards, volume, operator information on tank. | | |
| Corrective Action: | Install signs/markers to comply with Rule 210.d. | Date: | 07/20/2019 |
| Type | WELLHEAD | | |
| Comment: | Sign posted at entrance to location. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|-----------------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 5 | | |
| Comment: | 1-6" flowline from wellhead to separator. 1-1" flowline from separator to pumpjack engine fuel gas. 1-1" flowline from separator to heated produced water tank fuel gas. 1-6" flowline from separator to meter house. 1-6" flowline from meter house to offsite dogleg. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | On separator stack and heated produced water tank. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |

| | | | |
|--------------------|------------------------|-------|--|
| Comment: | Plumbed to surface. | Date: | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | Not currently running. | Date: | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|------------------|---------|------------------|
| OTHER | 1 | OTHER | HEATED STEEL AST | | , |
| Comment: | Tank missing labeling, volume, contact information. See CA under signs/markers. *thief hatch left open on tank. | | | | |
| Corrective Action: | Close gauge hatches when not accessing tank per Rule 605.a.(9) | | | | Date: 06/21/2019 |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| Date: | | | | |

Venting:

| | |
|--------------------|----|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | |
| Date: | |

Flaring:

| | |
|--------------------|--|
| Type | |
| Comment: | |
| Corrective Action: | |
| Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 258094 | Type: | WELL | API Number: | 067-08322 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Compaction | Pass | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | Ditches | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402083040 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4856771 |
| 687904953 | No tank labeling. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4856762 |
| 687904954 | Open thief hatch. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4856763 |