

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2019

Submitted Date:

06/27/2019

Document Number:

687905041**FIELD INSPECTION FORM**

Loc ID 326512 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Roland, Kandis		kroland@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89125	WELL	PR	03/08/2000	GW	067-08229	HUBER-BURKETT 3-25	PR

General Comment:

[Site inspection with photos at the end of this report.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action:
 Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Ancillary equipment	# 1				
Comment:	Wellhead.				
Corrective Action:		Date:			
Type: Pump Jack	# 1				
Comment:					
Corrective Action:		Date:			
Type: Bird Protectors	# 1				
Comment:	On separator stack.				
Corrective Action:		Date:			
Type: Bradenhead	# 1				
Comment:	PVC bradenhead access.				
Corrective Action:		Date:			
Type: Flow Line	# 5				
Comment:	1-3" flowline from wellhead to separator. 1-2" flowline from wellhead to separator. 1-1" flowline from separator to pumpjack engine fuel gas. 1-3" flowline from separator dump valve to offsite produced water gathering system. 1-4" flowline from separator to offsite dogleg.				
Corrective Action:		Date:			
Type: Vertical Heated Separator	# 1				
Comment:					
Corrective Action:		Date:			
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 89125 Type: WELL API Number: 067-08229 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905042	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864298