

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2019

Submitted Date:

06/21/2019

Document Number:

688304903

**FIELD INSPECTION FORM**

Loc ID 309596 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10691  
Name of Operator: PHOENIX RESOURCES LLC  
Address: 5566 S SYCAMORE STREET  
City: LITTLETON State: CO Zip: 80120

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Heffner, Taylor	303-219-3362	theffner@phxresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218136	WELL	DM	06/07/1993	GW	073-06121	NEWBY 6-12	DM

**General Comment:**

MIT Inspection, failed on domestic gas well to be converted to TA status well per COGCC Engineering.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	303-219-3362		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	steel panels in pasture		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 218136 Type: WELL API Number: 073-06121 Status: DM Insp. Status: DM

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Failed Form 21 is attached. Low pressure gas returned to truck tank for about 20 minutes. One-hundred-thirty BBLs of water used to load hole but did not load hole. Casing was on vacuum after taking hose off.

Corrective Action: Contact [dnr\\_cogccengineering@state.co.us](mailto:dnr_cogccengineering@state.co.us) with resolution plan.

Date: 07/05/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402084502	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858263">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858263</a>
688304976	Phoenix Resources Newby 6-12 Form 21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858249">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858249</a>
688304977	Phoenix Resources Newby 6-12 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858250">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858250</a>
688304978	Phoenix Resources Newby 6-12 wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858251">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858251</a>
688304979	Phoenix Resources Newby 6-12 contractors	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858252">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858252</a>