

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2019

Submitted Date:

06/28/2019

Document Number:

696600213

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312653 _____ Wentzel, Dougo _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222088	WELL	PR	03/01/2017	GW	077-08690	CASTLE ROCK 7-14	PR

General Comment:

This is a follow up inspection from Doc#675002128 .Dated 4/05/19 Required Corrective Action (s) items noted in previous inspections have been satisfied.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Corrective actions made		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911 / 1-800-891-6191		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	TRASH		
Comment:	Corrective actions made		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 222088 Type: WELL API Number: 077-08690 Status: PR Insp. Status: PR

Producing Well

Comment: Producing Well

Corrective Action:

Date:

Well Stimulation

Stimulation Company: _____

Stimulation Type: _____

Observation:

Other: _____

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
		Compaction				
Berms	Pass					

Comment: At time of inspection stormwater erosion appears to be controlled.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Thursday) (6/27/19) at approximately (1423), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Laramie) (Castle Rock 7-14), (API #077-08690) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection no compliance issues were observed: Corrective actions from previous inspection have been made: (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC r (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	06/27/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600214	Inspection 696600213 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864352