

Inspection Photos
Location Name: Falcon Seaboard 11-90-12 #5
API: 05-051-06139



Stained soil to the southwest of the #5 well head.



Illegible label on chemical injection system for #3 well head.

Inspection Photos
Location Name: Falcon Seaboard 11-90-12 #5
API: 05-051-06139



Stained soil near truck load out.



Falcon Seaboard 11-90-12 #3 and #5 location photo.