

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2019

Submitted Date:

06/24/2019

Document Number:

687904967

FIELD INSPECTION FORM

Loc ID 333494 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89142	WELL	PR	01/01/2003	GW	067-08246	ARGENTA 34-10 32-2	PR
291758	WELL	PR	02/01/2011	GW	067-09383	ARGENTA 34-10 32-2A	PR

General Comment:

[Site inspection with photos at the end of this report.](#)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Tank labels not updated to reflect current operator, operator contact and/or emergency contact information.		
Corrective Action:	Update signs and markers to comply with Rule 210.d.	Date:	07/24/2019
Type	WELLHEAD		
Comment:	Signs posted at wellheads.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Contact information posted on wellhead signs.	Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused batteries sitting in meter house.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.	Date:	07/24/2019
Type	UNUSED EQUIPMENT		
Comment:	Argenta 34-10 32-2A has been converted over to plunger lift. Pumpjack is still on location and not in use. Pumpjack and related equipment need to be put back into service or removed from location.		
Corrective Action:	Remove unused equipment or return to service per Rule 603.f.	Date:	09/24/2019

Overall Good:

Spills:

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	TANK BATTERY		
Comment:	T-post and hog wire around produced water tank.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Pump Jack	# 1		
Comment:	Currently not in use and disconnected from wellhead. See unused equipment for CA.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	2 on separator stacks and 1 on heated produced water tank.		
Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:	2-3" flowlines from wellhead to separators. 1-2" flowline from wellhead to separator. 1-1" flowline from wellhead to pumpjack engine fuel gas. 1-1" flowline from separator to heated produced water tank fuel gas. 2-2" flowlines from separator dump valves to produced water tanks. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg. 1-4" flowline from separator/meter to offsite dogleg.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellheads.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 89142 Type: WELL API Number: 067-08246 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 291758 Type: WELL API Number: 067-09383 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for pumpjack engine oil tank.
Rip Rap	Pass					
Gravel	Pass					
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date:
Pits: NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402086183	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859598
687904968	Unused equipment pumpjack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859585
687904969	Unused equipment pumpjack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859586
687904970	Unused equipment batteries.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859587
687904971	Tank labels not up to date.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859588
687904972	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859589