

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2019

Submitted Date:

06/24/2019

Document Number:

693200356**FIELD INSPECTION FORM**

Loc ID 424630 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Arauzo, Steven		steven.arauza@state.co.us	West Environmental Protection Specialist
Caerus		COGCC.inspections@caerus oilandgas.com	All Piceance inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
464596	SPILL OR RELEASE	AC	05/23/2019		-	8512E flowline release	EG

General Comment:

COGCC joint inspection with EPS S. Arauzo, EPS J. Heil and Western Integrity Inspector R. Murray

Engineering Integrity Inspection performed on June 20, 2019. In response to initial form 19 spill report Doc # 402046587

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 2		corrective date
Comment:	Rat hole protectors, weld plates have come lose, repairs needed, see photo log		
Corrective Action:	Repair or replace rat hole covers		Date: 07/29/2019

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 464596 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Dump Line	1 of Lines	
----	-----------------	------------	--

Flowline DescriptionFlowline Type: Dump LineSize: 2"Material: Carbon SteelVariance: NoAge: 1-5 YrsContents: Produced WaterIntegrity SummaryFailures: OtherSpills: YesRepairs Made: YesCoatings: Yes ExternalH2S: NoCathodic Protection: NoPressure TestingWitnessed: No

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment: Establish root cause of the failure and submit a flowline pressure test that was performed before returning to service via Form 4

Corrective Action:

Date: 07/03/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402085744	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859063
693200357	424630	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4858545