

Inspection Photos
Location Name: Beaver Creek 0881 1-3H34
Location ID: 451938



Photo 1. Overview of location taken at entrance facing north.



Photo 2. Stained soil on location.



Inspection Photos
Location Name: Beaver Creek 0881 1-3H34
Location ID: 451938



Photo 3. Stained soil at wellhead, chemical containment full of stormwater.



Photo 4. Unused triplex jet pump with secondary containment holding stormwater.

