

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2019

Submitted Date:

07/02/2019

Document Number:

689802867**FIELD INSPECTION FORM**Loc ID: 449274 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Ash, Margaret		margaret.ash@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Colby, Lou		lou.colby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449275	WELL	PR	06/01/2018		057-06598	REU 0681 1-23H2	PR

General Comment:**COGCC Inspection Report 689802867 Summary**

On Wednesday 6/26/2019 at approximately 10:15, I, Inspector Emily Waldron, and Inspector Lou Colby conducted a joint field/stormwater/reclamation inspection at Sandridge Exploration & Production LLC Rabbit Ears 0681 23 449274 in Jackson County Colorado.

While there, we observed production.

During this inspection the following possible compliance issues were observed:

Frack sand mentioned in inspection from 11/1/2018 document number 689801879 appears to still be on location. See photos 2-4. If spilled, released or dumped onto ground surface follow material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector by 11/8/2018.

Tubing stored on location adjacent to pump jack. See photo 1. Comply with Rule 603.f by 8/2/2019.

Stormwater in berm. Loadout hose resting in stormwater. See photo 5. Install or repair required BMPs per Rule 1002.f by 8/2/2019.

Washout of access road observed on 5/3/2019 document number 689802625 appears to have had gravel added to roadway, no additional BMPs observed during this inspection. No additional vehicle tracking measures observed. Tracking onto Colorado State Highway 14 is continuing. Site degradation occurring. All location stormwater BMPs need maintenance. See photos 6-9. Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority. Install or repair required BMPs per Rule 1002.f. Install or repair required BMPs per Rule 1002.f by 5/6/2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689802867.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	405-429-5974	Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Frack sand mentioned in inspection from 11/1/2018 document number 689801879 appears to still be on location.		
Corrective Action:	If spilled, released or dumped onto ground surface follow material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector.	Date:	11/08/2018
Type	STORAGE OF SUPL		
Comment:	Tubing stored on location adjacent to pump jack.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/02/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Flare	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	#		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	OTHER	STEEL AST		,	
Comment:	675 BBL capacity					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Inadequate
Comment:	Stormwater in berm. Loadout hose resting in stormwater.			
Corrective Action:	Install or repair required BMPs per Rule 1002.f.			
			Date:	08/02/2019

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	OTHER	STEEL AST		,	
Comment:	675 BBL capacity					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Inadequate
Comment:	Stormwater in berm. Loadout hose resting in stormwater.			
Corrective Action:	Install or repair required BMPs per Rule 1002.f.			
			Date:	08/02/2019

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID: 449275	Type: WELL	API Number: 057-06598	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Washout of access road observed on 5/3/2019 document number 689802625 appears to have had gravel added to roadway, no additional BMPs observed during this inspection. No additional vehicle tracking measures observed. Tracking onto Colorado State Highway 14 is continuing.
Site degradation occurring. All location stormwater BMPs need maintenance.

Corrective Action: Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority. Install or repair required BMPs per Rule 1002.f.

Date: 05/06/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802868	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867532