

Inspection Photos

API: 05-071-06340

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/1/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 7/1/2019

Inspection Photos



Photo 1. Facing northwest at mouth of the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 7/1/2019

Inspection Photos



Photo 2. Culvert has been cleaned out since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 7/1/2019

Inspection Photos



Photo 3. Rock rip/rap was placed in drainage channel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 7/1/2019

Inspection Photos



Photo 4. The side of the road has been regraded. The side may need erosion controls to prevent erosion. (e.g. check dams)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 7/1/2019

Inspection Photos



Photo 5. The erosion channel at the southeast side of the location has been repaired. The area may need erosion controls to prevent erosion. (e.g. check dams)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 7/1/2019

Inspection Photos



Photo 6. Facing toward the location. Sediment has been removed behind the equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 7/1/2019