

# Inspection Photos

API: 05-071-06130

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/1/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 7/1/2019

## Inspection Photos



**Photo 1.** There were culverts cleaned out along the road. Scrap pieces of culvert remain near the culverts.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 7/1/2019



## Inspection Photos



**Photo 2.** There were culverts cleaned out along the road. Scrap pieces of culvert remain near the culverts.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 7/1/2019

## Inspection Photos



**Photo 3.** Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 7/1/2019



## Inspection Photos



**Photo 4.** Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 7/1/2019

## Inspection Photos



**Photo 5.** The oily waste appears to have been cleaned up since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 7/1/2019