

Inspection Photos

API: 05-071-07204

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/1/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 7/1/2019

Inspection Photos



Photo 1. The culvert is full of sediment at outlet at the location. Did not check inlet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 7/1/2019

Inspection Photos



Photo 2. Facing toward the location.



Inspection Photos



Photo 3. There is soil sloughing that occurred at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 7/1/2019

Inspection Photos



Photo 4. View of soil material that moved down the hill side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 7/1/2019

Inspection Photos



Photo 5. No freeboard marker was found in the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07204 | Date: 7/1/2019