

Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 1. Battery sign at entrance, location wells not clearly listed.



Photo 2. Condensate tank labeled as crude oil.



Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 3. Stormwater in condensate tank berm.



Photo 4. Frack tank stored on location.

Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 5. Drilling material pushed off edge of perimeter berm.



Photo 6. Close up of materials in photo 5.



Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 7. Close up of materials in photo 5.



Photo 8. Stained soil at wellhead.

Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 9. Stained soil at wellhead.



Photo 10. Stained soil at wellhead.



Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 11. Example of soil staining seen on entire location.



Photo 12. Example of soil staining seen on entire location.

Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 13. Frack sand spilled on location.



Photo 14. Frack sand spilled on location and an example of soil staining seen on entire location.